



**RS
MODELS**


Lightning P-322 II

scale 1/72

The P-322 designation was used for aircraft taken over by the USAAF after the RAF cancelled an order for 667 P-38 Lightnings in 1942. This order had been inherited from the French, and had been for a simplified version of the aircraft, without the turbo-superchargers used by all USAAF P-38s.

Before receiving its first Lightnings, the RAF had changed its order to include 146 Lightning Mk Is, as ordered by the French, and 524 Mk IIs, which would have closely resembled the P-38E. The USAAF took over the British order, and completed the 524 Mk IIs as standard P-38Fs and P-38Gs.

The earlier aircraft was also taken over. Twenty two were completed as ordered, and given the designation P-322-I. The remaining 121 were given "F" series engines, as used in American P-38s, although they still lacked the turbo-supercharger. These aircraft were given the designation P-322-II. In American service these aircraft were used as advanced trainers, providing an ideal way to introduce new pilots to the P-38 without the added complexity of the turbo-supercharger for them to worry about.




LEGEND

- | | | | | | | | | | |
|----------------|--|---------------------|-------------------|--------------------|---------------------------|-----------------|----------------|------|--|
| | | | | | | | | | |
| ohnout
bend | vtěsninové lepidlo
cyanoacrylate glue | odstranit
remove | upravit
reduco | vrtat
open hole | vyrobit
scatrach build | obtisk
decal | barva
color | film | |

POLYURETHAN PARTS (PUR)

PUR1 PUR2








CLEAR PART (C)




COLORS

	Černá Black		Červená Red
	Interiéř. žlutá Zinc Chromate		Bílá White
	Stříbrná Silver		Žlutá Yellow
	Plátno Linen		Pneumatiky Tyres Black
	Kůže Leather		Rezová Rust
	Hliníková Aluminium		Tmavý šedá Dark Grey
	Chromová Chrome		Kovová Gun metal

92096




STEP
6



(LEFT TAIL STRUCTURE)


STEP
8




STEP
7

(RIGHT TAIL STRUCTURE)



STEP
9




STEP
10






STEP
11





(LEFT ENGINE)




Lightning P-322 II (92096)





	Bílá - White
	Tmavě žlutá - Dark yellow
	Světle šedá - Sky type S
	Tmavě hnědá - Dark Earth
	Briská tmavě zelená
	Černá - Black



1 P-322-II Lightning, AF 196, used as a trainer in California during late 1943

2 P-322-II Lightning, AF 132, Arizona 1943

3 P-322-II Lightning, AF 116, Hamilton Field, 1942

Líghtning


Americký stíhací letoun / American fighter from WW II

3 obtiskové verze
3 decal version



P-322 II

The P-322 designation was used for aircraft taken over by the USAAF after the RAF cancelled an order for 667 Lightnings in 1942. This order had been inherited from the French, and had been for a simplified version of the aircraft, without the turbo superchargers used by all USAAF P-38s. Twenty two were completed as ordered, and given the designation P-322-I. The remaining 121 were given "F" series engines, although they still lacked the turbo-supercharger. These aircraft were given the designation P-322-II. In American service these aircraft were used as advanced trainers, providing an ideal way to introduce new pilots to the P-38 without the added complexity of the turbo-supercharger for them to worry about.



RS
MODELS

1:72 SCALE
PLASTIC KIT

92096